

Inspection Photos
Location Name: Bass N 14-10
Location ID: 330660



Photo 1: Wellhead Sign



Photo 2: TA Wellhead



Inspection Photos
Location Name: Bass N 14-10
Location ID: 330660



Photo 3: Tank Battery Sign



Photo 4: Tank Battery



Inspection Photos
Location Name: Bass N 14-10
Location ID: 330660



Photo 5: Tank Battery Sign



Photo 6: Tank Battery



Inspection Photos
Location Name: Bass N 14-10
Location ID: 330660




Photo 7: Storage of unused equipment




Photo 8: Storage of unused equipment



Inspection Photos
Location Name: Bass N 14-10
Location ID: 330660



Photo 9: Storage of unused equipment




Photo 10: Storage of unused equipment



Inspection Photos
Location Name: Bass N 14-10
Location ID: 330660



Photo 11: Storage of unused equipment




Photo 12: Gas meter no annually calibrated