

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/18/2022

Submitted Date:

05/19/2022

Document Number:

691201610

FIELD INSPECTION FORM

Loc ID 332971 Inspector Name: Graber, Candice (Nikki) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, KPK		cogcc@kpk.com	All KPK Inspections
Gorka, Ray		RGorka@kpk.com	KPK environmental

General Comment:

During a routine environment inspection of Facility ID 480225/ Remediation Project 19246 the inspector was approached by the landowner and directed to an area of reported staining and sheen on groundwater. See additional comments under spills/releases. Pictures attached to document site conditions at time of inspection. Corrective actions require 24 hour response from Operator.

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: The area indicated by the landowner exhibited visual staining (see attached photos) and an elevated PID reading. These soils were in contact with surface water. The reported sheen was not visible at the time of inspection.

Corrective Action: Operator shall immediately coordinate with the landowner and investigate the stained area to determine if it is petroleum impacted soils. If it is a reportable spill/release; reporting shall follow Rule 912. If this is not a reportable release, Operator shall provide documentation in a FIRR. Date: 05/20/2022

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403054908	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758328
691201611	Stained soil in Contact with Surface Water	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758315
691201612	Stained soil in Contact with Surface Water	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758316
691201613	Map	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5758317