

# Inspection Photos

May 25, 2022

Operator: Chevron USA Inc - #16700

Location ID: 314510

Location Name: Wilson Creek Unit-63N94W /34NENW

Inspection Document #: 702800263

Rio Blanco County, CO

NENW Section 34 T3N R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NENW

Location ID: 314510



**Photo 1.** Photo taken from the center of the Location shows the excavation around the wellhead. Fence panels completely enclose the area and the slope of the pit is sufficiently gently to allow for wildlife egress.



**Photo 2.** Refer to Photo 1 comments.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800263

## Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NENW

Location ID: 314510



**Photo 3.** Photo taken from the south of the Location shows a pile of material excavated from around the well. A straw wattle has been installed as a control measure to prevent E&P waste from migrating off Location.



**Photo 4.** Photo taken from the northwest of the Location shows a straw wattle in disrepair and not functioning to control sediment transport from the Location.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800263

Inspection Photos

Location Name: Wilson Creek Unit-63N94W /34NENW

Location ID: 314510



**Photo 5.** Photo taken from the northwest of the Location shows a straw wattle in disrepair and not functioning to control sediment transport from the Location.



**Photo 6.** Refer to Photo 5 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800263