

Inspection Photos

API: 071-06406

Operator: OGRIS OPERATING LLC

Inspection Date: 6/2/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 6/2/2022

Inspection Photos



Photo 1. Facing southwest at the beginning of the reclaimed access road. This area needs additional reseeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 6/2/2022

Inspection Photos



Photo 2. Facing south further along the road. The perennial vegetation is progressing well along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 6/2/2022

Inspection Photos



Photo 3. Facing west further along the reclaimed road. The perennial vegetation is progressing well along the reclaimed road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 6/2/2022

Inspection Photos



Photo 4. Facing south at the reclaimed location. The perennial vegetation is progressing well at the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06406 | Date: 6/2/2022