

Inspection Photos and Issue Report

7/11/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 414268

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Colorado Oil and Gas Conservation Commission

KNOX 03-08 PAD, #414268



Annotation Report

Created on July 12, 2022

Captured on July 11, 2022



Area

Label	Title	Area	Surface Area
1 	Interim Areas	1.83 acres	1.84 acres

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 1: Photos 1-2 taken from the northeast end of the Location. Photos provide an overview of the working pad from south, southwest, northwest to north.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



July 11, 2022



July 11, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 3: Single active well on the Location.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 4: Photos example showing the fence around the interim areas of the Location has not been maintained in proper functioning condition.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268




Photo 5: Photo shows starting point of the “Disturbance 1” (D1) transect on the southern interim areas of the Location, facing west.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



July 11, 2022



July 11, 2022

Photo 6: Photos show the interim areas of the location at the 50th point of the D1 transect, facing south, and north.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 7: Interim areas surface at the 50th point of the D1 transect.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 8: Photo shows the end point of the “Disturbance 1” (D1) transect on the southern interim areas of the Location, facing east.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268




Photo 9: Photo shows starting point of the “Disturbance 2” (D2) transect on the southwestern interim areas of the Location, facing northwest

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



July 11, 2022



July 11, 2022

Photo 10: Photos show the interim areas of the location at the 50th point of the D2 transect, facing southwest, and northeast.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 11: Interim areas surface at the 50th point of the D1 transect

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 12: Photo shows end point of the “Disturbance 2” (D2) transect on the southwestern interim areas of the Location, facing southeast.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 13: Photo shows starting point of the “Disturbance 3” (D3) transect on the northwestern interim areas of the Location, facing northeast

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



July 11, 2022



July 11, 2022

Photo 14: Photos show the interim areas of the location at the 50th point of the D3 transect, facing northwest and southeast.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 15: Interim areas surface at the 50th point of the D3 transect

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268




Photo 16: Photo shows end point of the “Disturbance 3” (D3) transect on the northwestern interim areas of the Location, facing southwest.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 17: Photo shows starting point of the “Reference Area” transect north of the Location, facing east.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 18: Photos shows at the 50th point of the Reference Area transect, facing North and South.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 19: Surface at the 50th point of the Reference Area transect

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 414268



Photo 20: Photo shows the end point of the “Reference Area” transect north of the Location, facing west.