

# Interim Reclamation and Stormwater Inspection

June 16, 2022

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 438066

Inspection Document #: 697504026

Weld County, CO

NENW Section 28 T12N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Railay West 2833-1NH  
Location ID: 438066



**Photo 1.** Photo taken from the southern interim reclamation area, facing West. Photo illustrates Operator has responded to the previous corrective action to perform additional interim reclamation activities. Germination of native species was observed.





Inspection Photos  
Location Name: Railway West 2833-1NH  
Location ID: 438066



**Photo 2.** Photo taken from the southern interim reclamation area, facing South. See comments under Photo 1.



**Photo 3.** Photo taken from the western interim reclamation area, facing East. See comments under Photo 1.



Inspection Photos  
Location Name: Railay West 2833-1NH  
Location ID: 438066



**Photo 4.** Photo taken from the interim reclamation area. Photo illustrates a List B Colorado noxious weed, toadflax.



**Photo 5.** Photo taken from the southeastern interim reclamation area. Photo illustrates a List B Colorado noxious weed, Canada thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504026



Inspection Photos  
Location Name: Railay West 2833-1NH  
Location ID: 438066



**Photo 6.** Photo taken from the southeastern well location, facing Southeast. Photo illustrates unused risers that are not properly abandoned per Rule 1105.



**Photo 7.** Photo taken from the southeastern well location, facing West. See comments under Photo 6.