

Inspection Photos and Issue Report

7/19/2022

Operator: LARAMIE ENERGY LLC # 10433

Location #312531

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312531



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Location facing east, southeast, southwest to west. Revegetation activities were conducted 2021; location is within its second growing season. Though desirable vegetative establishment is evident, germination has not been uniform and additional reclamation work will be likely. Additionally, evidence of grazing pressure from livestock is evident, and is likely hindering reclamation from progressing towards 1004 standards.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312531



July 19, 2022



July 19, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312531



Photo 3: Photos show examples of areas on the Location where uniform establishment does not appear to be progressing towards 1004 standards; evidence of grazing pressure from livestock is evident, and is likely hindering reclamation from progressing towards 1004 standards

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312531



Photo 4: Photo of the adjacent reference area for comparison to vegetation on the reclamation area.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #312531



Photo 5: Previous inspections required Operator to remove surface equipment remaining on the Location pursuant with Rule 1004.a. Photo shows riser equipment has not been removed per the corrective action, and 1004 Rules.