

Inspection Photos and Issue Report

7/19/2022

Operator: LARAMIE ENERGY LLC # 10433

Location #334537

Mesa County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #334537



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location facing south, southwest, northwest to north. Photos show interim reclamation work has been completed, and revegetation is in process.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #334537



July 19, 2022



July 19, 2022

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: LARAMIE ENERGY LLC # 10433
Location #334537



Photo 3: Photos examples showing Undesirable and Noxious plants (bind weed, musk thistle) establishing on the production/interim/remediation areas