

Inspection Photos

Location Name: New Cache FH NWSE PAD /8-14D

Location #: 309973



Photo #1

Cache 8-33 (05-123-25665) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 25 yds.



Photo #2

Cache 8-13, 8-24, 8-34, Cornish 8-53 Battery site

Active

Reference: Loc. #306312 For Battery info

Formerly served:

Cache 8-23, Cache 8-33 ; Plugged & Abandoned | PA