

Inspection Photos

API: 061-05145

Operator: WESTERN OPERATING COMPANY

Inspection Date: 8/10/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 8/10/2022

Inspection Photos



Photo 1. Facing south toward the location. The access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 8/10/2022

Inspection Photos



Photo 2. Facing southeast toward the location. The location has been recontoured and decompacted. Soils have not been seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 8/10/2022

Inspection Photos



Photo 3. Facing northeast toward the location. The location has been recontoured and decompacted. Soils have not been seeded and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05145 - Date: 8/10/2022