

Inspection Photos and Issue Report

8/15/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334765

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334765



August 15, 2022



August 15, 2022

Photo 1: Photo 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location #334765



August 15, 2022



August 15, 2022

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334765



August 15, 2022

Photo 3: Photo shows Russian Olive plant establishing on the southern interim area of the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334765



August 15, 2022



August 15, 2022

Photo 4: Photo taken from the northeast end of the Location (Location entrance). Photo shows stormwater runoff has resulted in erosion degradation on the slope.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources