

Final Reclamation Inspection

Date: 08/17/2022

Operator: GREAT WESTERN OPERATING COMPANY -10110

Location ID: 320369

Inspection Document #: 696105366

Adams County, CO

NWNE Section 7 T1S R67W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 1. Tank Battery/Location photo taken from western portion, facing northeast. Photo illustrates location has not been reclaimed with presence bare soil and weedy annual vegetation; e.g. kochia, russian thistle. Location highlighted in red, access road also used for new construction (Location ID#452914).

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 2. See comments in Photo 1. Photo facing east.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 3. See comments in Photo 1. Photo facing northeast.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 4. See comments in Photo 1. Photo facing northwest.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 5. See comments in Photo 1. Photo facing southwest.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 6. See comments in Photo 1. Photo facing southeast.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 7. See comments in Photo 1. Photo facing east.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 8. Access road photo taken from western portion of location/well, facing west. Photo illustrates access road has not been reclaimed, e.g. gravel/road base removed, regraded, revegetated.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 9. See comments in Photo 8. Photo facing northwest.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 10. See comments in Photo 8. Photo facing east.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 11. Location/well photo taken from southern portion, facing north. Photo illustrates location has subsidence around old well head, highlighted in red.

Inspection Photos

Location Name: STONEHOCKER-61S67W 7NWNE

Location ID: 320369



Photo 12. See comments in Photo 11. Photo facing northwest.