

Final Reclamation Inspection

Date: 08/17/2022

Operator: GREAT WESTERN OPERATING LLC -10110

Location ID: 335863

Inspection Document #: 696105367

Adams County, CO

NWNW Section 7 T1S R67W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sauvage 12-7
Location ID: 335863



Photo 1. Location photo taken from northern portion, facing south. Photo illustrates location has not been reclaimed with presence of gravel/road base and annual weedy vegetation; e.g. kochia and russian thistle.

Inspection Photos
Location Name: Sauvage 12-7
Location ID: 335863



Photo 2. See comments in Photo 1.

Inspection Photos
Location Name: Sauvage 12-7
Location ID: 335863



Photo 3. Location photo taken from southern portion, facing southeast. Photo illustrates location has not been reclaimed with presence of gravel/road base. Red implement on location is property of surface owner (highlighted in red).

Inspection Photos
Location Name: Sauvage 12-7
Location ID: 335863



Photo 4. See comments in Photo 3. Photo facing north.

Inspection Photos
Location Name: Sauvage 12-7
Location ID: 335863



Photo 5. See comments in Photo 3. Photo facing southwest.

Inspection Photos
Location Name: Sauvage 12-7
Location ID: 335863



Photo 6. Location photo taken from southern portion, facing north. Photo illustrates location access road has not been reclaimed with presence of gravel/road base(highlighted in red).