

# Inspection Photos and Issue Report

8/17/2022

Operator: CAERUS PICEANCE LLC #10456

Location #478266

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #478266



**Photo 1:** Signage missing from Location entrance.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #478266



**Photo 2:** Soil salvage and location constriction in process.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC #10456  
Location #478266



August 17, 2022



August 17, 2022

**Photo 3:** Photos examples of erosion logs observed at base of soil stockpiles, and along the perimeter of the Location.