

Inspection Photos
Location Name: Southeast Spargo 1
Location ID: 322118



IMG 01
Well sign



IMG 02
Location overview




IMG 03
Location overview




IMG 04
Rig anchor



IMG 05
Weeds at crude oil tank



IMG 06
Tank label



IMG 07
Trash



IMG 08
Trash



IMG 09
Trash



IMG 10
Wellhead