

# Inspection Photos

September 28, 2022

Operator: Argali Exploration Company - #3975

Location ID: 313400

Location Name: Simpson-68N90W /25NWNW

Inspection Document #: 702800780

Moffat County, CO

NWNW Section 25 T8N R90W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**


Department of Natural Resources

Inspection Photos  
Location Name: Simpson-68N90W /25NWNW  
Location ID: 313400



**Photo 1.** Photo taken from the south shows an overview of the Location.

Inspection Photos  
Location Name: Simpson-68N90W /25NWNW  
Location ID: 313400



**Photo 2.** Photo shows production equipment.



**Photo 3.** Photo shows production equipment.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702800780

Inspection Photos  
Location Name: Simpson-68N90W /25NWNW  
Location ID: 313400



**Photo 4.** Photo shows production equipment. The plants at the right of the photo are Canada thistle (List B Noxious).



**Photo 5.** Photo shows an anchor marker in disrepair at the south of the Location.

Inspection Photos  
Location Name: Simpson-68N90W /25NWNW  
Location ID: 313400



**Photo 6.** Photo taken from the northwest of the Location shows areas seeded with perennial grasses and adjacent cultivated cropland.



**Photo 7.** Photo shows areas at the north of the Location seeded with perennial grasses.