

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335400



Photo #7926 From entrance to location.



Photo #7927 From entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335400



Network: Oct 4, 2022 at 12:40:35 PM MD
Local: Oct 4, 2022 at 12:40:35 PM MD

Photo #7928 From entrance to location.



Network: Oct 4, 2022 at 12:41:07 PM MD
Local: Oct 4, 2022 at 12:41:07 PM MD

Photo #7931 Undesirable plant species in tank containment.

Inspection Photos

Location Name: CAERUS PICEANCE LLC COUEY-66S92W /32NWNW

Location ID: 335400



Photo #7932 Undesirable plant species in tank containment.



Photo #7933 Undesirable plant species in tank containment