

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NWSE**

**Location ID: 335308**



**Photo #8002 From entrance to location.**



**Photo #8003 From entrance to location.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NWSE

Location ID: 335308



**Photo #8005 Undesirable plant species and stained soils in tank containment.**



**Photo #8006 Undesirable plant species.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC BENZEL-66S93W /26NWSE

Location ID: 335308



Photo #8007 Undesirable plant species



Photo #8008 Stained soils and Undesirable plant species.