

# Final Reclamation Inspection

August 1st, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323366

Inspection Document #: 701900501

SENE Section 30 T4N R67W

Corey McDonough  
Reclamation Contractor, COGCC




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources


Inspection Photos  
Location Name: Brown McCarty 30-5  
Location ID: 323366



**Photo 1.** 2021 aerial imagery of the well pad and access road. Note: tank battery remains for the shut in Brown McCarty 30-43 well API #123-21840.



Inspection Photos  
Location Name: Brown McCarty 30-5  
Location ID: 323366



**Photo 2.** Overview photo of the well pad, access road and reference area taken from directly above the disturbance using a drone. Note: well pad and access road appear consistent with adjacent crop reference area.



Inspection Photos  
Location Name: Brown McCarty 30-5  
Location ID: 323366



**Photo 3.** Overview photo of the tank battery that remains for the shut in Brown McCarty 30-43 well. No signs of erosion or stormwater issues observed.