

Inspection Photos
Location Name: Champlin 1-1(Her)
Location ID: 320245



Photo#1 Tanks.



Photo#2 Stained soil next to tank.

Inspection Photos
Location Name: Champlin 1-1(Her)
Location ID: 320245



Photo#3 Separator & meter run.




Photo#4 weeds next to separator

Inspection Photos
Location Name: Champlin 1-1(Her)
Location ID: 320245



Photo#5 chemical tank outside containment.



Photo#6 Meter out of calibration.

Inspection Photos
Location Name: Champlin 1-1(Her)
Location ID: 320245



Photo#7 Stained soil in separator house.



Photo#8 storage in side separator house.

Inspection Photos
Location Name: Champlin 1-1(Her)
Location ID: 320245



Photo # 9 pump jack.