

Inspection Photos

Loc: 307032

Operator: SIMCOE LLC

Inspection Date: 11/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 307032 | Date: 11/16/2022

Inspection Photos



Photo 1. Facing west along the access road. The road has been repaired since the previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 11/16/2022

Inspection Photos



Photo 2. There is still debris at the culvert inlet that should be removed.



Photo 3. The culvert outlet is still partially filled in with sediment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 11/16/2022

Inspection Photos



Photo 4. Facing west toward the location which is fenced and gate is closed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 11/16/2022

Inspection Photos



Photo 5. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 307032 | Date: 11/16/2022