

Inspection Photos

Loc: 480335

Operator: LOGOS OPERATING LLC

Inspection Date: 11/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 480335 | Date: 11/16/2022

Inspection Photos



Photo 1. Sign is posted at meter shed. **BONDAD 33-9 #5**



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 480335 | Date: 11/16/2022

Inspection Photos



Photo 2. There is stormwater directed toward the open top pit and has deposited sediment up against the berm. Stormwater should be directed around the location along with proper BMP's



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 480335 | Date: 11/16/2022