

Interim Reclamation and Stormwater Inspection

November 8, 2022

Operator: GADECO LLC - 10673

Location ID: 317527

Inspection Document #: 697504383

Weld County, CO

SWNW Section 26 T9N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GRAEFE #1
Location ID: 317527



Photo 1. COGCC drone aerial imagery from November 8, 2022. Photo illustrates the Operator has failed to perform subsequent reclamation after Remediation Project #10043 was completed.

