

# Final Reclamation and Stormwater Inspection

Date: 11/16/2022

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 320472

Inspection Document #: 696105596

Adams County, CO

SE Section 26 T1S R66W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources



**Photo 1.** Taken from the south end of the location, facing north. Photo illustrates that all oil and gas equipment has been removed. A vegetation assessment will be conducted at a later date to ensure compliance with Rule 1004 standards.





**Photo 2.** Taken from northern end of tank battery location, facing east. Photo illustrates undesirable vegetation (e.g. russian thistle and kochia) observed within reclaimed area.



Inspection Photos  
Location Name: Maul 2  
Location ID: 320472



**Photo 3.** Facing south, see comments in Photo 2.



Inspection Photos  
Location Name: Maul 2  
Location ID: 320472



**Photo 4.** Facing north, see comments in Photo 2.



Inspection Photos  
Location Name: Maul 2  
Location ID: 320472



**Photo 5.** Looking towards well location, facing north. See comments in Photo 2.



Inspection Photos  
Location Name: Maul 2  
Location ID: 320472



**Photo 6.** Taken from the northern portion of the well location, facing south. See comments in Photo 2.

Inspection Photos  
Location Name: Maul 2  
Location ID: 320472



**Photo 7.** Taken from the eastern portion of the well location, facing west. See comments in Photo 2.