

Inspection Photos

API: 071-06427

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/28/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06427 | Date: 11/28/2022

Inspection Photos



Photo 1. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06427 | Date: 11/28/2022

Inspection Photos



Photo 2. Along the main road at Lat/Long:37.14473,-104.67269. There is erosion along the road and stormwater is not being diverted off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06427 | Date: 11/28/2022

Inspection Photos



Photo 3. Along the main road at Lat/Long:37.14490,-104.67420. There is a deep erosion channel along the road that needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06427 | Date: 11/28/2022