

# Final Reclamation Inspection

October 20th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 322552

Inspection Document #: 701900754

SENE Section 30 T7N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Eaton Country Club 1  
Location ID: 322552



**Photo 1.** 2021 aerial imagery of the well pad and tank battery.  
Note: well pad is on a golf course.



Inspection Photos  
Location Name: Eaton Country Club 1  
Location ID: 322552



**Photo 2.** Overview photo of the well pad taken at ground level from the southern edge facing north.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number:  
701900754



Inspection Photos  
Location Name:Eaton Country Club 1  
Location ID: 322552



**Photo 3.** Overview photo of the tank battery taken at ground level from the eastern edge facing southwest.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number:  
701900754



Inspection Photos  
Location Name:Eaton Country Club 1  
Location ID: 322552



**Photo 4.** Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Eaton Country Club 1  
Location ID: 322552



**Photo 5.** Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: There is evidence of drill rows and crimp mulch at the tank battery location. Gravel was also observed at the tank battery location (see photo 6).



Inspection Photos  
Location Name: Eaton Country Club 1  
Location ID: 322552



**Photo 6.** Gravel remains at the tank battery location.