

Final Reclamation Inspection

October 20th, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 323638

Inspection Document #: 701900761

NESE Section 2 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**


Department of Natural Resources

Inspection Photos
Location Name: Kielian 2-1
Location ID: 323638



Photo 1. 2020 aerial imagery of the well pad. Note: tank battery highlighted in blue is no longer associated with the PDC well. Great Western last operator out.

Inspection Photos
Location Name:Kielian 2-1
Location ID: 323638



LOCATION ID: 323639
GREAT WESTERN OPERATING COMPANY LLC
LOCATION NAME: KIELIAN-64N67W #2SESE
[Location on Google Earth](#)
[Location on Google Maps](#)
Double-click to open link (https://cogcc.state.co.us/cogis/FacilityDetail.asp?facid=323639&TYPE=LOCATION)

Photo 2. COGCC GIS overview showing Great Western as operator of the tank battery.

Inspection Photos
Location Name:Kielian 2-1
Location ID: 323638



Photo 3. Overview photo of the well pad taken at ground level from the eastern edge facing west. Note: well pad disturbance falls within a storage area on a large residential lot.

Inspection Photos
Location Name:Kielian 2-1
Location ID: 323638




Photo 4. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name:Kielian 2-1
Location ID: 323638



Photo 5. Cardinal photos taken at ground level from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad is dominated by musk thistle.

Inspection Photos
Location Name:Kielian 2-1
Location ID: 323638



Photo 6. Well pad reference area.