

# Inspection Photos

November 28, 2022

Operator: Caerus Piceance LLC - #10456

Location ID: 334566

Location Name: GRASS MESA RANCH-67S93W/9NWNE

Inspection Document #: 702800976

Garfield County, CO

NWNE Section 9 T7S R93W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: GRASS MESA RANCH-67S93W/9NWNE  
Location ID: 334566



**Photo 1.** Photo taken from the east shows an overview of production areas.

## Inspection Photos

Location Name: GRASS MESA RANCH-67S93W/9NWN

Location ID: 334566



**Photo 2.** Photo shows fluid leaking from a produced water/condensate tank drain.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800976



## Inspection Photos

Location Name: GRASS MESA RANCH-67S93W/9NWN

Location ID: 334566



**Photo 3.** Refer to Photo 2 comment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800976

Inspection Photos  
Location Name: GRASS MESA RANCH-67S93W/9NWNE  
Location ID: 334566



11/28/22  
6991,-107.777870  
257° W



Photo 4. Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800976



## Inspection Photos

Location Name: GRASS MESA RANCH-67S93W/9NWNE

Location ID: 334566



**Photo 5.** Photo shows interim areas at the north of the location are vegetated with perennial grasses and shrubs.



**Photo 6.** Photo shows interim areas at the southwest of the location are vegetated with perennial grasses



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800976