

Inspection Photos

November 23, 2022

Operator: TEP Rocky Mountain LLC - #96850

Location ID: 311677

Location Name: HARRIS-67S94W/5SWNE

Inspection Document #: 702800968

Garfield County, CO

SWNE Section 5 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 1. Photo show an overview of northern production areas.



Photo 2. Photo shows an overview of southern production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800968

Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 3. Photo shows unmarked anchors to the west of the wells.



Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 4. Photo taken from the northern edge of the pad shows the northeastern portion of the pad has not been reclaimed. Photo also shows storage of equipment.



Photo 5. Photo taken from the northern edge of the pad shows the northwestern portion of the pad has not been reclaimed.

Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 6. Photo shows unreclaimed areas at the north of the location.



Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 7. Photo shows an overview of the eroding cut slope at the east of the location.



Photo 8. Photo shows a close-up of the eroding cut slope at the east of the location. Note exposed roots indicating soil loss.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800968

Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 9. Photo shows the cut slope to the south of the location behind the separators. Note rocks fallen within separator area past jersey barrier.



Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 10. Photo taken 5/27/2022 from inspection #700700789 shows approximately three rocks have fallen over the jersey barrier from the cut slope.



Photo 11. Photo from 11/23/22 inspection shows additional rocks have fallen over the jersey barrier from the cut slope indicating continued erosion of slopes.

Inspection Photos
Location Name: HARRIS-67S94W/5SWNE
Location ID: 311677



Photo 12. Photo shows equipment stored throughout the location.