

Final Reclamation Inspection

December 15, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 330420

Inspection Document #: 697504454

Weld County, CO

SESE Section 3 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-KNOX #16-3
Location ID: 330420



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the well location (red circle). The associated access road was also utilized for the northern well which will be addressed under that well and the associated tank battery is still active.

Inspection Photos
Location Name: HSR-KNOX #16-3
Location ID: 330420



Photo 2. Photo taken from the well location, facing North. Photo illustrates there is some establishment of grass species observed but it is predominately bare ground.

Note- vehicle traffic (not from COGCC) and prairie dog burrows. Also, portions of the photo are of the access road that was reclaimed back in 2019; whereas, the well location was plugged back in 2013.



Photo 3. Photo taken from the well location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: HSR-KNOX #16-3
Location ID: 330420



Photo 4. National Wetlands Inventory aerial illustrates Riverine habitat, Freshwater Emergent and Freshwater Forested/Shrub wetland downgradient of location.

Inspection Photos
Location Name: HSR-KNOX #16-3
Location ID: 330420



Photo 5. Google Earth aerial imagery from 1999 illustrating the well location disturbance extent.