

Final Reclamation Inspection

December 15, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 332954

Inspection Document #: 697504459

Weld County, CO

NWSE Section 3 T5N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SHUR VIEW #23-3
Location ID: 332954



Photo 1. COGCC GISOnline aerial imagery from 2019 illustrates the well location (red circle), access road and associated tank battery.

Inspection Photos

Location Name: SHUR VIEW #23-3

Location ID: 332954



Photo 2. Photo taken from the western disturbance near the active tank battery, facing Southeast. Photo illustrates the limited establishment of grass species observed and it is predominately bare ground.



Photo 3. Photo taken from a portion of the western access road, facing East. See comments under Photo 2.

Inspection Photos
Location Name: SHUR VIEW #23-3
Location ID: 332954



Photo 4. Photo taken from the associated tank battery, facing East. See comments under Photo 2.



Photo 5. Photo taken from the associated tank battery, facing North. See comments under Photo 2.

Note- Operator should have seeded perpendicular to the slope to minimize potential erosion.

Inspection Photos
Location Name: SHUR VIEW #23-3
Location ID: 332954



Photo 6. Photo taken from a portion of the eastern access road, facing East. See comments under Photo 2.



Photo 7. Photo taken south of the well location, facing North. Photo illustrates the well location. See comments under Photo 2.

Inspection Photos
Location Name: SHUR VIEW #23-3
Location ID: 332954



Photo 8. National Wetlands Inventory aerial illustrates Riverine habitat, Freshwater Emergent and Freshwater Forested/Shrub wetland downgradient of location.