

# Final Reclamation Inspection

October 19th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 323020

Inspection Document #: 701900742

SWNW Section 21 T5N R65W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Schneider 1  
Location ID: 323020



**Photo 1.** 2021 aerial imagery of the well pad and tank battery.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number:  
701900742



Inspection Photos  
Location Name: Schneider 1  
Location ID: 323020



**Photo 2.** Overview photo of the reclaimed well pad taken at ground level from the eastern edge looking west. Note: well pad now resides in an industrial storage area.



Inspection Photos  
Location Name: Schneider 1  
Location ID: 323020



**Photo 3.** Overview photo of the tank battery taken at ground level from the northern edge facing south.



Inspection Photos  
Location Name: Schneider 1  
Location ID: 323020



**Photo 4.** Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Schneider 1  
Location ID: 323020



**Photo 5.** Cardinal photos taken at ground level from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery shows no desirable species and is dominated by kochia.