

Operator: Extraction Oil & Gas Inc
Location Name: LEECH-61S66W 26SENW
Loc ID: 320530
Inspection: 696105608



Exhibit A – Location recontoured, graded and seeded (View 1)



Exhibit B – Location recontoured, graded and seeded (View 2)



Exhibit C – Access Road recontoured, graded and seeded

CA: *This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve months of plugging on non-cropland. Well was plugged 02/28/2020. During this inspection, COGCC Staff observed that portions of the access road (e.g gravel/road base) remain evident, the access road has not been recontoured to reflect reference areas, and the location has not revegetated as undesirable vegetation (e.g. kochia and russian thistle) were observed throughout.*

CA Resolution: Reclamation operations were completed on this location and access road which included: recontouring, grading and seeding in accordance with rule 1004. Operator will continue to monitor and manage this location until 1004 standards are met, including stormwater and weed management.