

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Linc Den (303) 894-2100 00572588	
API No. 05- 061 - 6484		LEASE NAME: HIGH PLAINS DRIFTER #2	
LOCATION: NWNW11-195-45W		OPERATOR: CAV. & CAV	
DATE: 10-29-96		INSPECTOR: R. Vansickle	
Insp. Type: SR	Insp. Status: PA	PA: <input checked="" type="radio"/> (Y) <input type="radio"/> (N)	Pass/Fail: <input checked="" type="radio"/> (P) <input type="radio"/> (F) Viol.: Y <input type="radio"/> (N) NOV: Y <input type="radio"/> (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)		
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)		
Fire Walls/Berms/Dikes (Rule 604)		
General Housekeeping (Rule 603.G)		
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)	Reclaimed, grass. remain. Treater # 2 2505 ✓	
Miscellaneous		

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site

DEC 2 1996