

# COLORADO OIL & GAS CONSERVATION COMMISSION

## FIELD INSPECTION REPORT

NOV 09 1995



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80202 (303) 733-7300	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		 00572587	
API No. 05- 061 - 6484		LEASE NAME: HIGH PLAINS DRIFTER #2	
LOCATION: NWNW11-19S-45W		OPERATOR: CAVANAUGH & CAVANAUGH	
DATE: 10-27-95		INSPECTOR: R. Vansickle	
Insp. Type: ID	Insp. Status: SI	PA: Y    N	Pass/Fail: P (F)    Viol. (Y)    N
NOV: Y    N			

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210)	None.	✓
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904)	None.	
<b>Fences</b> (Rule 604.C.(3), 1003.A)	None.	
<b>Tank Battery Equipment</b> (Rule 604)	Pmpy unit, 2 3005, vert. H-T.	✓
<b>Fire Walls/Berms/Dikes</b> (Rule 604)	None.	✓
<b>General Housekeeping</b> (Rule 603.G)	OK.	
<b>Spills (Oil/Water)</b> (Rule 908)	None.	
<b>Bradenhead</b> (Rule 207)	—	
<b>Drilling Well/Workover</b> (Rule 315)	—	
<b>Surface Rehabilitation</b> (Rule 317)	—	
<b>Miscellaneous</b>	Rods & thg in hole.	✓

<b>CORRECTIVE ACTION REQUIRED:</b> MIT, Produce or Plug.	
<b>Date Corrective Action Required By:</b> 4-30-96	<b>Date Remedied:</b>

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File    Green - Operator    Canary - Well Site

BOB VANSICKLE 719/336-2843