

# Final Reclamation Inspection

September 27, 2022

Operator: SNYDER OIL CORP - 80530

Location ID: 409212

Inspection Document #: 708000133

Weld County, CO

NESW Section 4 4N64W 6

Kasen Huwa  
Reclamation Contractor, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: CONNELL #4-1114  
Location ID: 409212



**Photo 1.** Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and access road (white arrow).

Inspection Photos  
Location Name: CONNELL #4-1114  
Location ID: 409212



**Photo 2.** COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (south center) and flowlines (black lines).

Inspection Photos  
Location Name: CONNELL #4-1114  
Location ID: 409212



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle). Tank Battery is addressed in Location 319183 report.

Inspection Photos  
Location Name: CONNELL #4-1114  
Location ID: 409212



**Photo 4.** Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates good growth on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.