

# Final Reclamation Inspection

September 23, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 330145

Inspection Document #: 708000140

Weld County, CO

SENW Section 17 3N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



**COLORADO**


**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-LDS #6-17  
Location ID: 330145




**Photo 1.** Google Earth aerial imagery taken 8/2018 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and approximate flowlines (red line).



**Photo 2.** COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dot), tank battery (east center) and flowlines (black lines). Flowline abandonment form has not been submitted.





**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Illustrates growth on and around the well location (red circle) and flowline (red line). Tank Battery is addressed in Location 428321 report.





**Photo 4.** Zoomed in Orthomosaic drone aerial imagery taken from 200 ft (Sept. 2022). Photo illustrates growth on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.