

Final Reclamation Inspection

October 05, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 306360

Inspection Document #: 708000143

Weld County, CO

SWNE Section 11 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**


Department of Natural Resources

Inspection Photos
Location Name: MILLAGE C 11-17
Location ID: 306360



Photo 1. Google Earth aerial imagery taken 6/2016 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and approximate flowlines (red line).

Location ID: 306360






Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested and mature crop growth on and around the well location (red circle), flowline (red line), and access road (blue line). Access road is shared with active agriculture. Tank Battery is addressed in Location 305601 report.

Inspection Photos
Location Name: MILLAGE C 11-17
Location ID: 306360



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates mature crop growth on and around the well location (red circle).