

Final Reclamation Inspection

October 05, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 406226

Inspection Document #: 708000153

Weld County, CO

NENE Section 11 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: JOHN CROISSANT UNIT 1
Location ID: 406226




Photo 1. Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and well location access road (white arrow).

Inspection Photos
Location Name: JOHN CROISSANT UNIT 1
Location ID: 406226




Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (north center) and flowlines (black lines).

Inspection Photos
Location Name: JOHN CROISSANT UNIT 1
Location ID: 406226



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle) and access road (blue line). Access road is shared with active agriculture. Tank Battery is addressed in Location 305601 report.

Inspection Photos
Location Name: JOHN CROISSANT UNIT 1
Location ID: 406226



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.