

# Final Reclamation Inspection

October 05, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 329195

Inspection Document #: 708000159

Weld County, CO

SENE Section 14 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STINAR \*14-8  
Location ID: 329195



**Photo 1.** Google Earth aerial imagery taken 8/2011 during active operations. Photo illustrates the well location (red circle), tank battery (red square), flowline (red line), and well location access road (white arrow).

Inspection Photos  
Location Name: STINAR \*14-8  
Location ID: 329195



**Photo 2.** COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (red rectangle) and flowlines (black lines).

Inspection Photos  
Location Name: STINAR \*14-8  
Location ID: 329195



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle) and access road (blue line). Tank Battery is addressed in Location 323230 report. Agriculture irrigation well near site (white arrow)

Inspection Photos  
Location Name: STINAR \*14-8  
Location ID: 329195



**Photo 4.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.

Inspection Photos  
Location Name: STINAR \*14-8  
Location ID: 329195



**Photo 5.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around access road. Road does not appear to be present and has been reclaimed (area below blue line). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.

N →



**Photo 6.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around access road. Road does not appear to be present and has been reclaimed (area below blue line). Agriculture irrigation well (white arrow).