

Final Reclamation Inspection

October 05, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 309878

Inspection Document #: 708000161

Weld County, CO

SWNE Section 9 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SLEDGE C 9-28
Location ID: 309878



Photo 1. Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and approximate flowlines (red line).

Inspection Photos
Location Name: SLEDGE C 9-28
Location ID: 309878




Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (south center) and flowlines (black lines).

Inspection Photos
Location Name: SLEDGE C 9-28
Location ID: 309878



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates non-agricultural growth on and around well location (red circle), tank battery (red rectangle), access road (white arrow), and approximate flowlines (red line).



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates non-agricultural growth on and around the well location (red oval). Still some bare dirt visible although minimal.



Photo 5. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates the tank battery area (red rectangle) has not been reclaimed.