

Final Reclamation Inspection

October 05, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 323144

Inspection Document #: 708000165

Weld County, CO

SENW Section 9 4N64W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SMITH 3
Location ID: 323144



Photo 1. Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), access road (white arrow), and approximate flowlines (red line).

Inspection Photos
Location Name: SMITH 3
Location ID: 323144



Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), tank battery (center) and flowlines (black lines). Flowline abandonment form has not been submitted.

Inspection Photos
Location Name: SMITH 3
Location ID: 323144



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates growth on and around the well location (red circle), flowline (red line), and tank battery (red rectangle). Similar growth to range land near it.

Inspection Photos
Location Name: SMITH 3
Location ID: 323144



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates growth similar to adjacent range land around the well location (red circle).



Photo 5. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates less growth than surrounding range land on the tank battery (red rectangle).