

Final Reclamation Inspection

October 05, 2022

Operator: NOBLE ENERGY INC- 100322

Location ID: 323133

Inspection Document #: 708000167

Weld County, CO

NENW Section 9 4N64W 6

Kasen Huwa

Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SMITH 2
Location ID: 323133



Photo 1. Google Earth aerial imagery taken 7/2019 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and approximate flowlines (red line).

Inspection Photos
Location Name: SMITH 2
Location ID: 323133



Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (close to center) and flowlines (black lines).

Inspection Photos
Location Name: SMITH 2
Location ID: 323133




Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle) and flowlines (red line). Tank Battery (red rectangle) is addressed in Location 309878 report. Access road still visible (blue line).



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates lack of full crop growth on and around the well location (red circle).