

Final Reclamation Inspection

October 05, 2022

Operator: AMOCO PRODUCTION COMPANY -
2500

Location ID: 406217

Inspection Document #: 708000171

Weld County, CO

SWNE Section 4 2N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: JERALD E STUGART ET AL UN 1

Location ID: 406217




Photo 1. Google Earth aerial imagery taken 9/1999 during active operations. Photo illustrates the well location (red circle).

Inspection Photos
Location Name: JERALD E STUGART ET AL UN 1
Location ID: 406217



Photo 2. COGCC Online Map aerial imagery 2019 with subject wells (red rectangle), related wells (red dots outside of red rectangle), tank battery (southern center) and flowlines (black lines).

Inspection Photos

Location Name: JERALD E STUGART ET AL UN 1

Location ID: 406217



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates growth on and around the well location (red circle). Tank Battery is addressed in Location 327566 report.

Inspection Photos

Location Name: JERALD E STUGART ET AL UN 1

Location ID: 406217



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.