

Final Reclamation Inspection

October 05, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 327566

Inspection Document #: 708000172

Weld County, CO

SENE Section 4 2N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MOSER FARMS *4-1
Location ID: 327566




Photo 1. Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red rectangle), and well location access road (white arrow).

Inspection Photos
Location Name: MOSER FARMS *4-1
Location ID: 327566



Photo 2. COGCC Online Map aerial imagery 2019 with subject wells (red rectangle), related wells (red dots outside of red rectangle), tank battery (southern center) and flowlines (black lines).

Inspection Photos
Location Name: MOSER FARMS *4-1
Location ID: 327566

N →



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates growth on and around the well location (red circle), flowlines (red lines), tank battery (red rectangle) and access road (white arrow).

Inspection Photos
Location Name: MOSER FARMS *4-1
Location ID: 327566



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates growth on and around the well location (red circle).



Photo 5. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates bare ground on and around the tank battery (red rectangle).



Photo 6. Google Earth imagery from 6/10/21 shows tank battery (red rectangle) was in use by land owner for agriculture storage.