

# Final Reclamation Inspection

October 05, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 332303

Inspection Document #: 708000175

Weld County, CO

NENW Section 5 2N65W 6

Kasen Huwa  
Reclamation Contractor, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: B & M \*21-5  
Location ID: 332303



**Photo 1.** Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and well location access road (white arrow).

Inspection Photos  
Location Name: B & M \*21-5  
Location ID: 332303



**Photo 2.** COGCC Online Map aerial imagery 2019 with subject wells (red rectangle), related wells (red dots), tank battery (north center) and flowlines (black lines).

Inspection Photos  
Location Name: B & M \*21-5  
Location ID: 332303



**Photo 3.** Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates growth on and around the well location (red circle), flowlines (red line), and access road (blue line). Tank Battery is addressed in Location 305817 report.



Inspection Photos  
Location Name: B & M \*21-5  
Location ID: 332303



**Photo 4.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Shows signs of sparse crop coverage and undesirable plants are more prevalent.



Inspection Photos  
Location Name: LLLLL  
Location ID: 000000



**Photo 5.** Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates access road (blue line) is somewhat visible.