

Final Reclamation Inspection

October 05, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 305817

Inspection Document #: 708000176

Weld County, CO

NWNE Section 5 2N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: B & M *31-5
Location ID: 305817



Photo 1. Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and well location access road (white arrow).

Inspection Photos
Location Name: B & M *31-5
Location ID: 305817




Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (north center) and flowlines (black lines).

Inspection Photos
Location Name: B & M *31-5
Location ID: 305817




Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates mature crop (ready to harvest) on and around the well location (red circle), road (blue line) and flowline. Tank battery (red rectangle) and most of access road are between two fields in the corners, rangeland.

Inspection Photos
Location Name: B & M *31-5
Location ID: 305817



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates mature crop (ready to harvest) on and around the well location (red circle). At well location undesirable plants are more prevalent than crops.



Photo 5. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates some growth on and around the tank battery (red rectangle) but bare dirt prevalent.