

Final Reclamation Inspection

October 05, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 331925

Inspection Document #: 708000179

Weld County, CO

NENE Section 4 2N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MOSER FARMS *4-11
Location ID: 331925




Photo 1. Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and flowlines (red line).

Inspection Photos
Location Name: MOSER FARMS *4-11
Location ID: 331925



Photo 2. COGCC Online Map aerial imagery 2019 with subject well (blue dot), related wells (red dots), tank battery (southeast) and flowlines (black lines).

N →




Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle) and flowlines (red line). No access road visible. Tank Battery is addressed in Location 327566 report.

Inspection Photos
Location Name: MOSER FARMS *4-11
Location ID: 331925



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.