

Final Reclamation Inspection

October 05, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 327245

Inspection Document #: 708000181

Weld County, CO

NWNW Section 5 2N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: B & M USX X *5-4
Location ID: 327245



Photo 1. Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), well location access road (white arrow), and flowline (red line).

Inspection Photos
Location Name: B & M USX X *5-4
Location ID: 327245



Photo 2. COGCC Online Map aerial imagery 2019 with related wells (red dots), subject well (blue dot), tank battery (near northeast corner) and flowlines (black lines).

Inspection Photos
Location Name: B & M USX X *5-4
Location ID: 327245



Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle), flowline (red line), and access road (white arrow). Tank Battery is addressed in Location 305817 report.

Inspection Photos
Location Name: B & M USX X *5-4
Location ID: 327245



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.