

Final Reclamation Inspection

October 05, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP -
47120

Location ID: 305704

Inspection Document #: 708000183

Weld County, CO

SENW Section 5 2N65W 6

Kasen Huwa
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: B & M *22-05
Location ID: 305704



Photo 1. Google Earth aerial imagery taken 10/2015 during active operations. Photo illustrates the well location (red circle), tank battery (red square), and flowline (red line).

Inspection Photos
Location Name: B & M *22-05
Location ID: 305704



Photo 2. COGCC Online Map aerial imagery 2019 with related wells (red dots), subject well (blue dot), tank battery (near northeast corner) and flowlines (black lines).

N →




Photo 3. Orthomosaic drone aerial imagery taken from 200 ft (Oct. 2022). Illustrates growth on and around the well location (red circle) and flowline (red line). No access road visible. Tank Battery is addressed in Location 305817 report.

Inspection Photos
Location Name: B & M *22-05
Location ID: 305704



Photo 4. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop on and around the well location (red circle). Shows signs of sparse crop coverage and undesirable plants are more prevalent.

N →



Photo 5. Zoomed in Orthomosaic taken from 200 ft (Oct. 2022). Illustrates harvested crop growth along flowline (red line). Appears similar to rest of area, however crop height cannot be fully evaluated. Another inspection is required when crop is actively growing.